



MONTHLY OPERATION REPORT FOR CONSECUTIVE SYSTEMS THAT DO NOT TREAT WATER

See page 2 for instructions.

I. General Information for the Month/Year of: 03/23

Consecutive System Name: _____ **PWS Identification Number:** 4131424

Consecutive System Type: Community Non-Transient Non-Community Transient Non-Community

Number of Service Connections at End of Month: _____ **Total Population Served at End of Month:** 5800

Consecutive System Owner: Town of Surfside

Contact Person: John Nelson **Contact Person's Title:** Assistant Public Works Director

Contact Person's Mailing Address: 9293 Harding Ave **City:** Surfside **State:** FL **Zip Code:** 33154

Contact Person's Telephone Number: 305 861 4862 **Contact Person's Fax Number:** _____

Contact Person's E-Mail Address: jnelson@townofsurfside.fl.gov

II. Daily Data for the Month/Year of: _____

Type of Disinfectant Residual Maintained in Distribution System: Free Chlorine Combined Chlorine (Chloramines) Chlorine Dioxide

Day of the Month	Lowest Residual Disinfectant Concentration at Remote Point in Distribution System, mg/L	Emergency or Abnormal Operating Conditions; Repair or Maintenance Work that Involves Taking Water System Components Out of Operation	Day of the Month	Lowest Residual Disinfectant Concentration at Remote Point in Distribution System, mg/L	Emergency or Abnormal Operating Conditions; Repair or Maintenance Work that Involves Taking Water System Components Out of Operation
1	0.42	Biscaya Drive Fire HyDrant (1453)	17	0.54	Biscaya Drive Fire HyDrant (1453)
2	0.36	88 and aBBOT Fire HyDrant	18	0.37	88 and aBBOT Fire HyDrant
3	0.50	9301 collins community c. Fire HyDrant	19	0.48	9301 collins community c. Fire HyDrant
4	0.37	700-95 ST Bay Dr Fire HyDrant	20	0.36	700-95 ST Bay Dr Fire HyDrant
5	0.56	Biscaya Drive Fire HyDrant (1453)	21	0.39	Biscaya Drive Fire HyDrant (1453)
6	0.52	88 and aBBOT Fire HyDrant	22	0.47	9301 collins community c. Fire HyDrant
7	0.42	9301 collins community c. Fire HyDrant	23	0.52	88 and aBBOT Fire HyDrant
8	0.40	700-95 ST Bay Dr Fire HyDrant	24	0.42	700-95 ST Bay Dr Fire HyDrant
9	0.33	Biscaya Drive Fire HyDrant (1453)	25	0.47	Biscaya Drive Fire HyDrant (1453)
10	0.36	88 and aBBOT Fire HyDrant	26	0.50	9301 collins community c. Fire HyDrant
11	0.52	9301 collins community c. Fire HyDrant	27	0.38	88 and aBBOT Fire HyDrant
12	0.43	700-95 ST Bay Dr Fire HyDrant	28	0.36	700-95 ST Bay Dr Fire HyDrant
13	0.37	Biscaya Drive Fire HyDrant (1453)	29	0.37	Biscaya Drive Fire HyDrant (1453)
14	0.48	88 and aBBOT Fire HyDrant	30	0.39	9301 collins community c. Fire HyDrant
15	0.37	9301 collins community c. Fire HyDrant		0.42	88 and aBBOT Fire HyDrant
16	0.34	700-95 ST Bay Dr Fire HyDrant			

III. Certification by Authorized Representative

I am duly authorized to sign this report on behalf of the consecutive system identified in Part I of this report. I certify that the information provided in this report is true and accurate to the best of my knowledge and belief.

John Nelson 3/31/23 John H Nelson Assistant Public Works Director

Signature and Date Printed or Typed Name License Number or Title